

09/420 887

co/c



BLAKELY SOKOLOFF TAYLOR & ZAFMAN

A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS

TELEPHONE (408) 720-8300

FACSIMILE (408) 720-8383

BSTZ_MAIL@BSTZ.COM

WWW.BSTZ.COM

INTELLECTUAL PROPERTY LAW

SILICON VALLEY

1279 OAKMEAD PARKWAY
SUNNYVALE, CALIFORNIA 94085-4040

OTHER OFFICES

LOS ANGELES, CA

ORANGE COUNTY/COSTA MESA, CA

SAN JOSE, CA

DENVER, CO

PORTLAND/BEAVERTON, OR

SEATTLE, WA

May 17, 2005

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Re: **CERTIFICATE OF CORRECTION**
U. S. Letters Patent No. 6,889,284
Issued: May 3, 2005
For: **METHOD AND APPARATUS FOR
SUPPORTING SDRAM MEMORY**
Inventor: Nizar et al.
Our File No. 42390.P7149

*Certificate
JUN 20 2005
of Correction*

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent.
This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C.
Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP

Edwin H. Taylor
Reg. No. 25,129

EHT/kh
Enclosures

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,889,284 *B1*

DATED : May 3, 2005

INVENTOR(S) : Nizar et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 4, at line 67, delete "1" and insert ---1--.

In column 6, at the end of line 18 after "row.", insert --MA[7.0]=Byte Masks for DQA bus.--.

In column 8, at line 42 after "generated", insert --by--.

In column 10, at line 43, delete "representative" and insert --responsive--.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,889,284

Certificate of Correction (PTO Form 1050)-Amended

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,889,284 *1*

DATED : May 3, 2005

INVENTOR(S) : Nizar et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 4, at line 67, delete "1" and insert --1--.

In column 6, at the end of line 18 after "row.", insert --MA[7.0]=Byte Masks for DQA bus.--.

In column 8, at line 42 after "generated", insert --by--.

In column 10, at line 43, delete "representative" and insert --responsive--.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,889,284

Certificate of Correction (PTO Form 1050)-Amended